

Elito (ES/GS/EW/GW093) Lamping Information

1. NB - Ensure electrical supply is isolated before fitting and/or making any electrical connections.
2. Loosen the two screws on the side of the front casting but do not remove.
3. Slide the rear casting up the lampholder cables to provide sufficient clearance to fit the lamp.
4. Fit the lamp into the lampholder.
5. LVR versions - Connect the spades connectors to the screws on the back of the lamp ensuring they are tight. Slide the lamp at 90° to the front casting past the pivots. When clear of the pivots rotate the lamp a further 90° so that the front of the lamp is located into the aperture of the casting.
6. MHC versions - Fit the lamp into the lampholder ensuring that the pins are located correctly and the lamp is fully pushed into the lampholder.
7. MHR versions - Fit the lamp into the lampholder by locating the pins into the receptacles in the lampholder and turn to locate correctly. Slide the lamp at 90° to the front casting past the pivots. When clear of the pivots rotate the lamp a further 90° so that the front of the lamp is located into the aperture of the casting.
8. Replace the rear casting and tighten screws ensuring that the lampholder cables are not trapped in any way.
9. Reconnect the electrical supply and test the installation.